


CERTIFICATION:


All sampling plans, sample collection procedures, sample preparation procedures, extraction procedures, and instrumental/chemical analysis procedures used to assess or characterize the PCB contamination at the cleanup site, are on file at the location designated in the certificate, and are available for EPA inspection.


Files are located at the following location:

Cocciardi and Associates, Inc.  
1337 Veterans Memorial Drive  
Jessup, PA 18434

Under civil and criminal penalties of law for the making or submission of false or fraudulent statements or representations (18 U.S.C. 1001 and 15 U.S.C. 2615), I certify that the information contained in or accompanying this document is true, accurate, and complete. As to the identified section(s) of this document for which I cannot personally verify truth and accuracy, I certify as the company official having supervisory responsibility for the persons who, acting under my direct instructions, made the verification that this information is true, accurate, and complete.

 Joe Cordaro 1/16/17  
(Signature and printed name of owner of property) Date  
Lace Building Affiliates, LP, Chester Springs, PA

 Joseph A. Cocciardi 2/2/17  
(Signature and printed name of party authoring cleanup plan) Date  
Joseph A. Cocciardi, PhD, MS, CSP, CIH, REHS/RS

 Thomas Jimmie Jr. 1/13/17  
(Signature and printed name of party conducting cleanup) Date  
Datom Products, Inc., Dunmore, PA

List of Attachments: Attachment I: Sampling Plan  
Attachment II: Health and Safety Plan  
Attachment III: Sampling Mapping and Results  
Attachment IV: Laboratory Sampling Reports  
Attachment IVA: Laboratory Quality Control Documentation  
Attachment IVB: Laboratory Sampling Reports: Quality Control  
Replicate Sample Reports  
Attachment V: Landfill Permits

cc: PADEP Regional Office: Wilkes-Barre, PA  
City of Scranton: Department of Community & Economic Development